

TOOLMASTER



1MT x JT6 Drill Chuck Arbor

Suits Ø13mm Drill Chucks



TOOLMASTER 1MT x JT6 Drill Chuck Arbor

Description

Drill chuck arbors have one end which is the taper of the machine. The most common are Morse Tapers for mounting in a drill press spindle or lathe, or NT tapers for mounting in milling machines. The other end of the arbor is a short taper called a Jacobs Taper that is driven into the taper in the chuck body. The JT taper or Jacobs Taper is the most commonly used taper for mounting a drill chuck. The most common tapers used in Australia are JT2, JT3, JT4 & JT6

Features

- Hardened & precision ground

Specifications

ORDER CODE	D440
Long Taper (MT)	1MT
Short Taper (JT)	JT6
Suits Chuck Size (mm)	13
Threaded Shank	~