



TOOLMASTER

3MT x JT3 Drill Chuck Arbor

Suits Ø16mm Drill Chucks



TOOLMASTER 3MT x JT3 Drill Chuck Arbor

Description

Drill chuck arbors have one end which is the taper of the machine. The most common are Morse Tapers for mounting in a drill press spindle or lathe, or NT tapers for mounting in milling machines. The other end of the arbor is a short taper called a Jacobs Taper that is driven into the taper in the chuck body. The JT taper or Jacobs Taper is the most commonly used taper for mounting a drill chuck. The most common tapers used in Australia are JT2, JT3, JT4 & JT6

Features

- Precision ground and tanged

Specifications

ORDER CODE	D443A
Long Taper (MT)	3MT
Short Taper (JT)	JT3
Suits Chuck Size (mm)	16
Threaded Shank	~