

CNC PLASMA CABLE - UNIVERSAL

Plug & Cable complete with Spade connectors



CNC PLASMA CABLE - UNIVERSAL

Description

CNC Universal Plug & Cable to suit :
Unimig Razor 45, 80, 120
Hypertherm Powermax Series

For the remote start function.
Plug connection for plasma, spade connectors for CNC machine side connection
See downloads for connection diagram