

TOOLMASTER



R8 x JT3 Drill Chuck Arbor - 7/16" UNF Threaded Shank

Suits Ø16mm Drill Chucks



TOOLMASTER R8 x JT3 Drill Chuck Arbor - 7/16" UNF Threaded Shank

Description

Drill chuck arbors have one end which is the taper of the machine. The most common are Morse Tapers for mounting in a drill press spindle or lathe, or NT tapers for mounting in Milling machines. The other end of the arbor is a short taper called a Jacobs Taper that is driven into the taper of the chuck body. The JT taper or Jacobs Taper is the most commonly used taper for mounting a drill chuck. The most common tapers used in Australia are JT2, JT3, JT4 & JT6

Features

- Hardened & precision ground with 7/16" UNF drawbar

Specifications

ORDER CODE	D445
Long Taper (MT)	R8
Short Taper (JT)	JT3
Suits Chuck Size (mm)	16
Threaded Shank	7/16" UNF